


AD-A103 756

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON --ETC F/6 13/13
NATIONAL DAM SAFETY PROGRAM, ROCK ISLAND LAKE DAM (NJ 00819) WA--ETC(U)
AUG 81 W A GUINAN. DACW61-79-C-0011

UNCLASSIFIED

DAEN/NAP-53842/NJ00819-81/ NL

1 OF 1
ADA
03 110



END
DATE
FILMED
10-81
DTIC

AD A103756

LEVEL II



WALLKILL RIVER BASIN
ROCK ISLAND LAKE, SUSSEX COUNTY
NEW JERSEY

ROCK ISLAND LAKE DAM NJ 00819

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

DTIC
ELECT
SEP 4 1981

AUGUST 1981

D

REPT. NO: DAEN/NAP-53842/NJ00819-81/08

81 9 03.067

DTIC FILE COPY

x/b

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM	
1. REPORT NUMBER DAEN/NAP/53842/NJ00819-81/08	2. GOVT ACCESSION NO. AD-A103 756	3. RECIPIENT'S CATALOG NUMBER	
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Rock Island Dam, NJ00819 Sussex County, N.J.	5. TYPE OF REPORT & PERIOD COVERED FINAL	6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(s) Guinan, Warren, P.E.	8. CONTRACT OR GRANT NUMBER(s) DACW61-79-C-0011		
9. PERFORMING ORGANIZATION NAME AND ADDRESS Anderson-Nichols 150 Causeway St. Boston, Massachusetts	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS		
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection Division of Water Resources P.O. Box CNO29 Trenton, NJ 08625	12. REPORT DATE August, 1981	13. NUMBER OF PAGES 50	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106	15. SECURITY CLASS. (of this report) Unclassified	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.			
17. DISTRIBUTION STATEMENT (of the abstract entered in B1) National Dam Safety Program, Rock Island Lake Dam (NJ 00819) Walkkill River Basin, Rock Island Lake, Sussex County, New Jersey. Phase I Inspection Report.			
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.			
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams National Dam Safety Program Seepage Embankments Rock Island Dam, N.J. Visual Inspection Spillways Structural Analysis Ersoions			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report. → pag 1			



IN REPLY REFER TO

NAPEN-N

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE-2 D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, New Jersey 08621

31 AUG 1981

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Rock Island Lake Dam in Sussex County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Rock Island Lake Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate because a flow equivalent to 25 percent of the Spillway Design Flood (SDF) would cause the dam to be overtopped. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures and studies within six months from the date of approval of this report. Within three months of the consultant's findings remedial measures to ensure spillway adequacy should be initiated:

b. Within six months from the date of approval of this report the owner should engage a qualified professional consultant to perform the following:

(1) Evaluate the leakage into the spillway discharge pipe and design and oversee corrective measures as required.

(2) Design and oversee the procedure for the removal of brush, debris and trees from the downstream slope and for a distance of 25 feet from the downstream toe of the dam or to the property line whichever is the lesser distance.

(3) Design and oversee repairs for the eroded areas on the upstream slope of the dam and specify erosion protection for the upstream slope.

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

NAPEN-N.

Honorable Brendan T. Byrne

(4) Investigate the cause of the seepage and wet, soft areas at and downstream of the downstream toe of the dam and design remedial measures as required.

c. Within six months from the date of approval of this report the following remedial actions should be initiated:

(1) Begin a program of periodically checking the condition of the dam and monitoring the seepage and wet areas along and downstream of the downstream toe of the dam.

(2) Point the stone masonry headwall containing the spillway discharge pipes.

(3) Establish permanent cover along the crest after filling ruts with suitable material.

(4) Clear inlet box of debris.

d. Within one year from the date of approval of this report the owner should clear trees and brush on either side of the discharge channel for a distance of 100 feet from the toe of the dam or the property line whichever is the lesser.

e. The owner of the dam should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam within one year from the date of approval of this report.

f. An emergency action plan should be developed which outlines actions to be taken by the owner to minimize the downstream effects of an emergency at the dam within six months from the date of approval of this report.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Courter of the Thirteenth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

NAPEN-N

Honorable Brendan T. Byrne

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



ROGER L. BALDWIN

Lieutenant Colonel, Corps of Engineers
Commander and District Engineer

1 Incl

As stated

Copies furnished:

Mr. Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief
Bureau of Flood Plain Regulation
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

ROCK ISLAND LAKE DAM (NJ00819)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 23 April 1981 by Anderson-Nichols and Co., Inc., under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Rock Island Lake Dam, initially listed as a high hazard potential structure, but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in fair overall condition. The dam's spillway is considered inadequate because a flow equivalent to 25 percent of the Spillway Design Flood (SDF) would cause the dam to be overtopped. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures and studies within six months from the date of approval of this report. Within three months of the consultant's findings remedial measures to ensure spillway adequacy should be initiated:

b. Within six months from the date of approval of this report the owner should engage a qualified professional consultant to perform the following:

(1) Evaluate the leakage into the spillway discharge pipe and design and oversee corrective measures as required.

(2) Design and oversee the procedure for the removal of brush, debris and trees from the downstream slope and for a distance of 25 feet from the downstream toe of the dam or to the property line whichever is the lesser distance.

(3) Design and oversee repairs for the eroded areas on the upstream slope of the dam and specify erosion protection for the upstream slope.

(4) Investigate the cause of the seepage and wet, soft areas at and downstream of the downstream toe of the dam and design remedial measures as required.

c. Within six months from the date of approval of this report the following remedial actions should be initiated:

(1) Begin a program of periodically checking the condition of the dam and monitoring the seepage and wet areas along and downstream of the downstream toe of the dam.

(2) Point the stone masonry headwall containing the spillway discharge pipes.

(3) Establish permanent cover along the crest after filling ruts with suitable material.

(4) Clear inlet box of debris.

d. Within one year from the date of approval of this report the owner should clear trees and brush on either side of the discharge channel for a distance of 100 feet from the toe of the dam or the property line whichever is the lesser.

e. The owner of the dam should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam within one year from the date of approval of this report.

f. An emergency action plan should be developed which outlines actions to be taken by the owner to minimize the downstream effects of an emergency at the dam within six months from the date of approval of this report.

APPROVED:



ROGER L. BALDWIN
Lieutenant Colonel, Corps of Engineers
Commander and District Engineer

DATE:

31 Aug 81

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam:	Rock Island Lake
Identification No.:	Fed ID No. NJ00819
State Located:	New Jersey
County Located:	Sussex
Stream:	Wallkill River Tributary
River Basin:	Wallkill
Date of Inspection	April 23, 1981


ASSESSMENT OF GENERAL CONDITIONS

Rock Island Lake Dam is probably at least 50 years old and is in poor condition. It is a small dam, 500 feet long, 19.1 feet in height, and was initially rated as high hazard but downgraded to a significant hazard classification as a result of this inspection. Sixty percent of the downstream area at the toe is wet and seepage, noted by orange colored flocs, shows that water is passing through and under the dam. The three 12-inch concrete spillway pipe system is connected to a 20-inch RCP with a 24-inch RCP outlet that discharges beyond the toe of the dam. An 8-inch blowoff pipe also discharges through the 24-inch RCP. The downstream slope is covered with debris and dump materials. Brush and large trees are growing on the downstream face and at the toe. Erosion gullies have developed on the upstream slope and erosion has left patches of rip rap on the upstream slope. A small discharge of whitish foul-smelling effluent is coming from the 24-inch RCP spillway outlet. The spillway is capable of passing 24 percent of the Spillway Design Flood inflow hydrograph, which is one-half the Probable Maximum Flood, without overtopping. Therefore, the spillway is considered inadequate.

The owner should engage a professional engineer qualified in the design and construction of dams to accomplish the following in the near future: Investigate the adequacy of the spillway capacity and design and oversee remedial measures as needed; evaluate the leakage into the spillway discharge pipe; design and oversee the procedure for the removal of brush, debris, and trees from the downstream slope for a distance of 25 feet from the downstream toe of the dam or to the property line, whichever is less; design and oversee repairs for the eroded areas on the upstream slope of the dam and specify erosion protection for the upstream slope; and investigate the seepage and wet, soft areas at and downstream of the downstream toe of the dam and design remedial measures as required.

It is further recommended that the owner accomplish the following tasks as part of operation and maintenance procedures. Starting soon: Begin a program of periodically checking the condition of the dam and monitoring the seepage and wet areas along and downstream of the downstream toe of the dam; point stone masonry headwall containing the spillway discharge pipes; establish permanent cover along the crest after filling ruts with suitable material; clear inlet box of debris; and develop an emergency plan which outlines actions to be taken by the owner to minimize downstream effects of an emergency at the dam. In the near future: Develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam, and clear trees and brush on either side of the discharge channel for a distance of 100 feet from the toe of the dam or to the property line whichever is the lesser.

ANDERSON-NICHOLS & COMPANY, INC.

A handwritten signature in cursive script, reading "Warren A. Guinan".

Warren A. Guinan, P.E.
Project Manager
New Jersey 16848



February 17, 1981

OVERVIEW PHOTO
ROCK ISLAND LAKE DAM

CONTENTS

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY REPORT

ROCK ISLAND LAKE DAM FED ID NO. NJ00819

SECTION		<u>Page</u>
SECTION 1	PROJECT INFORMATION	
	1.1 <u>General</u>	
	1.2 <u>Project Description</u>	
	1.3 <u>Pertinent Data</u>	
SECTION 2	ENGINEERING DATA	
	2.1 <u>Design</u>	
	2.2 <u>Construction</u>	
	2.3 <u>Operation</u>	
	2.4 <u>Evaluation</u>	
SECTION 3	VISUAL INSPECTION	
SECTION 4	OPERATIONAL PROCEDURES	
	4.1 <u>Procedures</u>	
	4.2 <u>Maintenance of Dam</u>	
	4.3 <u>Maintenance of Operating Facilities</u>	
	4.4 <u>Warning System</u>	
	4.5 <u>Evaluation of Operational Adequacy</u>	
SECTION 5	HYDRAULIC/HYDROLOGIC	
SECTION 6	STRUCTURAL STABILITY	
SECTION 7	ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES	
	7.1 <u>Assessment</u>	
	7.2 <u>Recommendations/Remedial Measures</u>	
FIGURES	1. Essential Project Features	
	2. Essential Project Features	
	3. Regional Vicinity Map	
APPENDICES	1. Check List Visual Inspection	
	2. Photographs	
	3. Hydrologic Computations	
	4. HEC 1 Output	
	5. References	

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonable possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY INSPECTION PROGRAM
ROCK ISLAND LAKE POND DAM
FED ID NO. #NJ00819

SECTION 1
PROJECT INFORMATION

1.1 General

a. Authority. Authority to perform the Phase I Safety Inspection of Rock Island Lake Dam was received from the State of New Jersey, Department of Environmental Protection, Division of Water Resources by letter dated 12 December 1980 under Basic Contract No. FPM-39 and Contract No. A01093 dated 10 October, 1979. This Authority was given pursuant to the National Dam Inspection Act, Public Law 92-367 and by agreement between the State and the U.S. Army Engineers District, Philadelphia. The inspection discussed herein was performed by Anderson-Nichols & Company, Inc.

b. Purpose: The purpose of the Phase I Investigation is to develop an assessment of the general conditions with respect to the safety of Rock Island Lake Dam and appurtenances. Conclusions are based upon available data and visual inspection. The results of this study are used to determine any need for emergency measures and to conclude if additional studies, investigations, and analyses are necessary and warranted.

1.2 Project Description

a. Description of Dam and Appurtenances. Rock Island Lake Dam is a 500 foot long earth embankment dam with a hydraulic height of 18.1 feet and a structural height of 19.1 feet. The spillway is a concrete weir leading to three 12-inch concrete pipes, located at the left center of the dam, and connecting to a 20-inch RCP with a 24-inch reinforced concrete pipe outlet that discharges downstream of the toe of the dam. An 8-inch blow-off pipe also discharges through the 24-inch RCP. The dam's crest width ranges from 30 to 100 feet. The crest of the dam is bare and rutted because it serves as an access road to homes on the right (north) side of the lake. The dam's upstream face has a 3H:1V slope with small erosion gullies at and above the water line. The downstream embankment has a 2H:1V slope and is covered with extensive debris, including large boulders, brush, tree stumps, and trash. The downstream toe is wet and soft, with a high concentration of orange colored flocs.

b. Location. The dam is located on a tributary to the Wallkill River in Sparta Township, Sussex County, New Jersey. The dam is at 41° 02.5' north latitude and 74° 35.2' west longitude on the Franklin, N.J. Quadrangle. The dam may be reached by exiting from Interstate 80 on Route 15 north to Sparta, exiting right on Route 517 north at the center of Sparta, turning right immediately on Route 620 (Glen Road). Rock Island Dam is a left turn approximately 0.5 mile after Glen Road branches left from Milton Road. A location map has been included as Figure 3.

c. Size Classification. Rock Island Lake Dam is classified as being small in size on the basis of storage at the dam crest of 61 acre-feet, which is less than 1000 acre-feet but more than 50 acre-feet, and on the basis of its structural height of 19.1 feet, which is less than 40 feet, in accordance with criteria given in the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. Visual inspection of the downstream area shows that the failure of Rock Island Dam would cause the surface of the small pond about 200 feet downstream to rise about 5-1/2 feet. Two houses and a shed or garage are located downstream of the small pond. The porch, and presumably the first floor, elevation of the lower of the two houses, about 4 occupants, is about 5 feet above the present pond surface. Although damage to the lower house may be appreciable, few, if any, lives would be lost. Therefore, the dam is considered significant hazard.

e. Ownership. The dam is co-owned by Mr. Carl Aherns and Mr. Franz Montane. Information may be obtained by writing Mr. Aherns at Glen Road, Sparta, New Jersey.

f. Purpose. Mr. Aherns said that the dam was built to provide road access and to create a lake.

g. Design and Construction History. No information regarding the original plan or design of the dam was available.

h. Normal Operational Procedure. No operational procedures were disclosed for the dam.

i. Site Geology. No site specific geologic information (such as borings) was available at the time the dam was inspected. Information derived from the Geology of Franklin and part of Hamburg Quadrangles, New Jersey (Buddington and Baker, 1961) and Glacial Drift Map of New Jersey (Salisbury, Kummel, Peet and Whitson, 1902) indicates soils within the immediate site consist of glacial till over bedrock.

Bedrock was observed in one outcrop adjacent to the downstream toe of the dam during the site visit. The previously mentioned map indicates that bedrock in the area consists of medium granitoid gneiss of Precambrian age.

1.3 Pertinent Data

a. Drainage Area

0.09 square miles

b. Discharge at Damsite (cfs)

Maximum flood at damsite - unknown

Total ungated spillway capacity at maximum pool elevation (at top of dam) - 9

c. Elevation (ft. above NGVD)

Top of dam - 1251.1

Test flood (1/2 PMF) - 1251.9

Recreation pool (at time of inspection) - 1250

Spillway crest - 1250

Streambed in channel near the toe of the dam - 1233.0

Maximum tailwater - (estimated) - 1237.0

d. Reservoir (length in feet)

Length of maximum pool - 1000 (estimated)

Spillway crest - 900

e. Storage (acre-feet)

Spillway crest - 50

Test Flood (1/2 PMF) - 69

Top of dam - 61

f. Reservoir Surface (acres)

Top of dam - 11 (estimated)

Spillway crest - 10

g. Dam

Type - earth

Length - 500 feet

Height - 18.1 feet (hydraulic)

- 19.1 feet (structural)

Top width - ranges from 30 to 100 feet

Side slopes - upstream 3H:1V, downstream 2H:1V

Zoning - unknown

Impervious core - unknown

Cutoff - unknown

Grout curtain - unknown

h. Spillway

Type - Three 12-inch concrete pipes set in a stone masonry headwall connected to a 20-inch RCP and discharging through a 24-inch RCP

Length of weir - 3 feet

Crest elevation - 1250 feet NGVD

Low level outlet - one 8-inch diameter blowoff pipe
(see 1.2 i below)

U/S Channel - Rock Island Lake

D/S Channel - tributary to Wallkill River

i. Regulating Outlets

Type - one 8-inch diameter blow off pipe
connected to 24-inch RCP spillway outlet
pipe.

Length (estimated) - 60 feet

Access - along crest of dam to valve box on up-
stream side to the right of the spillway.

SECTION 2 ENGINEERING DATA

2.1 Design

No hydraulic, hydrologic, or other engineering data were disclosed. However a property map, showing some dimensions of the dam, was made available by Mr. Carl Aherns, a co-owner.

2.2 Construction

No recorded data concerning construction of the Rock Island Lake Dam were found.

2.3 Operation

No written operational data were found.

2.4 Evaluation

a. Availability. A search of the New Jersey Department of Environmental Protection files revealed no information.

b. Adequacy. Data obtained in the visual inspection are deemed adequate to complete this Phase 1 Inspection Report

SECTION 3 VISUAL INSPECTION

3.1 Findings

a. Dam. The downstream slope and downstream toe of the dam are covered with extensive debris, including large boulders, brush, tree stumps, leaves and a considerable amount of trash which makes it impossible to inspect the downstream slope adequately. It appeared during the site visit that dumping of debris over the crest had taken place over a considerable period of time. The area at the downstream toe is wet and soft for approximately sixty percent of the length of the dam. Several seeps were observed discharging water which had a pronounced chemical odor and a high concentration of orange colored flocs with no evidence of suspended fines. Near the center of the dam, the 24-inch-diameter reinforced concrete pipe (RCP) outlet, connected to the three 12-inch concrete spillway pipes, was discharging water with a strong chemical odor which flowed in the channel bypassing a small pond downstream from the dam. A large wet and soft area was observed approximately 50 feet downstream from the dam. This area was opposite the three 12-inch-diameter concrete pipes which are located on the upstream slope.

Trees are growing in the area at the downstream toe of the dam. Brush and small trees are growing on the upstream slope. Erosion has left sporadic patches of riprap on the upstream face and developed erosion gullies at and above the waterline.

The crest is bare and rutted because of vehicular traffic; the crest serves as access road to several houses on the right (north) side of the dam.

b. Appurtenant Structures. The inlet box leading to the three 12-inch-diameter concrete pipes is clogged with leaves and debris. The concrete of the structure is surface eroded and the mortar in the stone-masonry headwall is missing or cracked. The outlet for these pipes is a 24-inch RCP, located near the downstream toe.

c. Reservoir Area. The watershed above the lake is gently to moderately sloping and wooded. Several homes were noted around the perimeter of the reservoir. Slopes on the shore of the lake appear stable. No appreciable sedimentation was observed.

d. Downstream Channel. Erosion has occurred on the right and left banks of the channel immediately downstream from the 24-inch-diameter RCP. Approximately 150 feet downstream from the pipe, the stream flows adjacent to and around the toe of the slope of the dike which contains a downstream pond. Trees are growing on the banks of the channel downstream of the 24-inch RCP.

SECTION 4
OPERATIONAL PROCEDURES

4.1 Procedures

No formal operating procedures were revealed.

4.2 Maintenance of Dam

No formal maintenance procedures for the dam were found.

4.3 Maintenance of Operating Facilities

No formal maintenance procedures for the operating facilities were discovered.

4.4 Warning System

No description of any warning system was found.

4.5 Evaluation of Operational Adequacy

Because of the lack of operation and maintenance procedures, the remedial measures described in Section 7.2 should be implemented as described.

SECTION 5
HYDROLOGIC/HYDRAULIC

5.1 Evaluation of Features

a. Design Data. Because no original hydrologic/hydraulic design data were revealed, an evaluation of such data could not be performed.

b. Experience Data. No experience data were found.

c. Visual Inspection. The inlet box for the spillway pipes contain debris and sediment. The downstream outlet is a 24-inch RCP. At that time, this pipe was discharging a small quantity of whitish-colored, foul-smelling effluent. This may be caused by infiltration through the pipe joints of leachate from dumped material on the downstream face of the dam.

d. Rock Island Lake Dam Overtopping Potential. The hydraulic/hydrologic evaluation for the dam is based on a selected Spillway Design Flood (SDF) equal to one-half the Probable Maximum Flood (PMF) in accordance with the range of test floods given in the evaluation guidelines, for dams classified as significant hazard and small in size. The PMF was determined by application of a 24-hour Probable Maximum Precipitation of 22.2 inches to the SCS dimensionless unit hydrograph. Hydrologic computations are given in Appendix 3. The routed half-PMF peak discharge for the subject drainage area is 288 cfs.

Water will rise to a depth of 1.1 foot above the spillway crest before overtopping the low point on the dam embankment crest. Under this head the spillway capacity is 9 cfs, which is less than the selected SDF.

Flood routing calculations indicate that Rock Island Lake Dam will be overtopped for 6.8 hours to a maximum depth of 0.8 feet under half-PMF conditions. It is estimated that the spillway can pass 24 percent of the half-PMF inflow hydrograph without overtopping the dam. Thus, the spillway is considered inadequate.

e. Draw-down Capacity. If the low level outlet currently in place is fully operable and free of siltation, it is estimated that the pond can be drained in approximately 15 days, assuming no significant inflow. This time period is considered marginal for draining the reservoir under emergency conditions, but adequate, considering the small drainage area.

SECTION 6 STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability The presence of boulders, brush, leaves, and extensive debris on the downstream slope makes it impossible to make an adequate inspection of the embankment.

The soft, wet area and seepage at the downstream toe of the dam is indicative of seepage either through or under the dam which, if not properly controlled, could lead to failure of the dam by piping or sloughing of the downstream slope.

The trees growing at the downstream toe of the embankment and in the area downstream of the toe may blow over and pull out their roots or they may die with the result that their roots rot. In either case, serious seepage and erosion problems could result.

Erosion gullies which are developing on the crest and upstream face of the dam are susceptible to erosion by rainfall or by overtopping of the dam or wave action on the upstream face, and erosion could, in turn, lead to breaching of the dam.

Parts of the crest of the dam which are bare of vegetation would be susceptible to erosion if the dam were overtopped, which might, in turn, lead to breaching of the dam.

6.2 Design and Construction Data. No design or construction data pertinent to the structural stability of the dam are available.

6.3 Operating Records. No operating records pertinent to the structural stability of the dam were available.

6.4 Post-Construction Changes. No record of post-construction changes was available.

6.5 Seismic Stability - This dam is in Seismic Zone 1. According to the Recommended Guidelines, dams located in Seismic Zone 1 "may be assumed to present no hazard from earthquake provided static stability conditions are satisfactory and conventional safety margins exist." None of the visual observations made during the inspection are indicative of unstable slopes. However, because no data are available concerning the engineering properties of the embankment and foundation materials for this dam, it is not possible to make an engineering evaluation of the stability of the slopes or the factor of safety under static conditions.

SECTION 7
ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. Rock Island Lake Dam is estimated to be at least 50 years old and is in poor condition.

b. Adequacy of Information. The information available is such that the assessment of the dam must be based primarily on the results of the visual inspection.

c. Urgency. The recommendations made in 7.2.a and 7.2.b should be implemented by the owner as prescribed.

d. Necessity for Additional Data/Evaluation. The information available from the visual inspection is adequate to identify the potential problems which are listed in 7.2.a. These problems require the attention of a professional engineer who will have to make additional engineering studies to design or specify remedial measures to rectify the problems. If left unattended, the problems could lead to failure of the dam.

7.2 Recommendation/Remedial Measures

a. Recommendations. The owner should engage a professional engineer qualified in the design and construction of dams to accomplish the following in the near future:

- (1) Investigate the adequacy of the spillway capacity and design and oversee remedial measures as needed.
- (2) Evaluate the leakage into the spillway discharge pipe and design and oversee corrective measures as required.
- (3) Design and oversee the procedure for the removal of brush, debris and trees from the downstream slope and for a distance of 25 feet from the downstream toe of the dam or to the property line whichever is the lesser distance.
- (4) Design and oversee repairs for the eroded areas on the upstream slope of the dam and specify erosion protection for the upstream slope.
- (5) Investigate the cause of the seepage and wet, soft areas at and downstream of the downstream toe of the dam and design remedial measures as required.

b. Alternatives: None, however, if the dam and reservoir are considered non-essential, the dam could be breached and a bridge over the stream could be provided to replace the embankment.


c. Operating and Maintenance Procedures. The owner should accomplish the following in the time periods specified.

Starting soon:

- (1) Begin a program of periodically checking the condition of the dam and monitoring the seepage and wet areas along and downstream of the downstream toe of the dam.
- (2) Point the stone masonry headwall containing the spillway discharge pipes.
- (3) Establish permanent cover along the crest after filling ruts with suitable material.
- (4) Clear inlet box of debris.
- (5) Develop an emergency action plan which outlines actions to be taken by the owner to minimize downstream effects of an emergency at the dam.

In the near future:

- (1) Develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.
- (2) Clear trees and brush on either side of the discharge channel for a distance of 100 feet from the toe of the dam or the property line whichever is the lesser.




NOTE:

SPILLWAY INLET PIPES CONNECTED TO DISCHARGE PIPE UNDER ROADWAY AS PER PROPERTY MAP OBTAINED FROM CO-OWNER. (7/7/81)

Anderson-Nichols & Co, Inc		U.S. ARMY ENGINEER DIST PHILADELPHIA	
BOSTON		CORPS OF ENGINEERS	
MASSACHUSETTS		PHILADELPHIA, PA	
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS			
ROCK' ISLAND LAKE DAM			
PLAN			
ROCK ISLAND LAKE		NEW JERSEY	
		SCALE NOT TO SCALE	
		DATE: JUNE 1981	

FIGURE - 1



Anderson-Nichols & Co, Inc		U.S. ARMY ENGINEER DIST PHILADELPHIA	
BOSTON		CORPS OF ENGINEERS	
MASSACHUSETTS		PHILADELPHIA, PA	
NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS			
ROCK ISLAND LAKE DAM			
ELEVATION			
ROCK ISLAND LAKE		NEW JERSEY	
		SCALE NOT TO SCALE	
		DATE JUNE 1981	

FIGURE-2



SCALE IN MILES



MAP BASED ON STATE OF NEW JERSEY
OFFICIAL MAP & GUIDE.

Anderson-Nichols & Co., Inc.		U.S. ARMY ENGINEER DIST. PHILADELPHIA	
BOSTON		CORPS OF ENGINEERS	
MASSACHUSETTS		PHILADELPHIA, PA.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
ROCK ISLAND LAKE DAM			
LOCATION MAP			
ROCK ISLAND LAKE		NEW JERSEY	
		SCALE: 1" = 4 Miles Approx.	
		DATE: JUNE 1981	

APPENDIX 1

CHECK LIST

VISUAL INSPECTION

ROCK ISLAND LAKE

Check List
Visual Inspection
Phase 1

Name Dam Rock Island Lake Dam County Sussex State NJ(00819) Coordinators NJDEP
 Date(s) Inspection 2/17/81 4/23/81 Weather Cool & Overcast Rain, Overcast Temperature 45° 55°
 Pool Elevation at Time of Inspection 1250' NGVD Tailwater at Time of Inspection 1233' NGVD

Inspection Personnel:

<u>W. Guinan</u>	<u>F.D.Deane</u>
<u>S. Gilman</u>	<u>K.Stuart</u>
<u>R. Murdock</u>	

R. Murdock/K.Stuart Recorder

Owner not present

UNGATED SPILLWAY OUTLET WORKS

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

CONCRETE WEIR

3-foot wide concrete weir in poor condition leads to three 12-inch concrete pipes

Locate and clean outlet or replace spillway

APPROACH CHANNEL

Unobstructed on right side. Building foundation runs perpendicular to spillway at left abutment for approx. 25 feet

DISCHARGE CHANNEL

Outlet at center of dam - 24-inch reinforced concrete pipe. Discharging liquid smelling of chemicals. Maybe infiltrating through joints. Ground and rocks around discharge end are discolored and malodorous.

Investigate source of discharge.

BRIDGE AND PIERS OVER SPILLWAY

N/A

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None observed	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	Unable to observe toe, covered by leaves and debris.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Erosion along crest, upstream and downstream slopes. Trees and brush on upstream slopes, trees up to 16-inch diameter along toe.	Clear trees and brush.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal - Okay Vertical - Slight undulation in elevation along crest	
RIPPAP FAILURES	Riprap appears to be missing above water level. Some riprap noted on slope below water surface.	Provide erosion protection.

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
RAILINGS	None	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Some erosion evident on upstream slope adjacent to spillway intake.	
ANY NOTICEABLE SEEPAGE	Ground wet and soggy along majority of toe. Visible seepage at toe near outlet pipe. Standing water along toe near right abutment.	
STAFF GAGE AND RECORDER	N/A.	
DRAINS	None found	

DOWNSTREAM CHANNEL

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

Poor flowline meanders through woods.

CONDITION
(OBSTRUCTIONS,
DEBRIS, ETC.)

Moderately steep. Wooded.

SLOPES

One home approx. 6 feet above pond
150 yards d/s. Estimate 4 persons.

APPROXIMATE NO.
OF HOMES AND
POPULATION

RESERVOIR

VISUAL EXAMINATION OF

OBSERVATIONS

REMARKS OR RECOMMENDATIONS

Gradual to moderately sloped, wooded, some structures present adjacent to reservoir.

SLOPES

No appreciable sedimentation observed.

SEDIMENTATION

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	None found
REGIONAL VICINITY MAP	Prepared for this report
CONSTRUCTION HISTORY	None found
TYPICAL SECTIONS OF DAM	None found
HYDROLOGIC/HYDRAULIC DATA	None found
OUTLETS - PLAN	
- DETAILS	None found
- CONSTRAINTS	
- DISCHARGE RATINGS	
RAINFALL/RESERVOIR RECORDS	None found

ITEM		REMARKS
DESIGN REPORTS	None found	
GEOLOGY REPORTS	None found	
DESIGN COMPUTATIONS		
HYDROLOGY & HYDRAULICS		
DAM STABILITY	None found	
SEEPAGE STUDIES		
MATERIALS INVESTIGATIONS		
BORING RECORDS		
LABORATORY	None found	
FIELD		
POST-CONSTRUCTION SURVEYS OF DAM	None found	
BORROW SOURCES	Unknown	

REMARKS

ITEM

MONITORING SYSTEMS

None found

MODIFICATIONS

None found

HIGH POOL RECORDS

None found

POST CONSTRUCTION ENGINEERING
STUDIES AND REPORTS

None found

PRIOR ACCIDENTS OR FAILURE OF DAM
DESCRIPTION
REPORTS

None found

MAINTENANCE
OPERATION
RECORDS

None found

ITEMS	REMARKS
SPILLWAY PLAN	
SECTIONS DETAILS	None found
OPERATING EQUIPMENT PLANS & DETAILS	None found

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 0.09 square miles, moderate slope,

wooded

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1250' NGVD (50

acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY) _____

Not applicable

ELEVATION MAXIMUM TEST FLOOD POOL: 1251.9' NGVD

ELEVATION TOP DAM: 1251.1' NGVD (61 acre-feet)

SPILLWAY CREST: Pipes broad-crested, concrete box with
one-foot stoplog notch.

a. Elevation 1250' NGVD

b. Type Stone masonry headwall with three 12-inch
concrete pipes connected to a 20-inch RCP
discharging through a 24-inch RCP

c. Width Three foot apron with training walls

d. Length 3 feet

e. Location Spillover near center of dam

f. Number and Type of Gates None

OUTLET WORKS: Blow-off pipe

a. Type One 8-inch pipe

b. Location Right of spillway

c. Entrance Invert Estimated at 1240.0' NGVD

d. Exit Invert 1236.6' NGVD


HYDROMETEOROLOGICAL GAGES: None

MAXIMUM NON-DAMAGING DISCHARGE: 9 cfs

APPENDIX 2

PHOTOGRAPHS

ROCK ISLAND LAKE



April 23, 1981

Spillway Intake



April 23, 1981

Crest of dam from left abutment



April 23, 1981

Upstream face, some riprap visible




April 23, 1981

Large wet area downstream of dam



April 23, 1981

Looking along toe toward 24-inch RCP spillway outlet pipe



April 23, 1981

Close-up view of 24-inch RCP spillway outlet pipe



April 23, 1981

Erosion in crest of dam directly above seep
at toe of slope



April 23, 1981

Close-up of seep



April 23, 1981

Wet area at toe of slope, orange flocs, no visible sedimentation or flow, leaves and brush obscure toe



April 23, 1981

View of extensive debris along downstream slope



April 23, 1981

Spillway pipe retreat channel




April 23, 1981

Discharge channel looking downstream

APPENDIX 3

HYDROLOGIC COMPUTATIONS

ROCK ISLAND LAKE



**NATIONAL PROGRAM OF INSPECTION OF
NON-FED. DAMS**


**ROCK ISLAND LAKE DAM
SPARTA TOWNSHIP, NEW JERSEY
REGIONAL VICINITY MAP**

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
PHILADELPHIA, PENNSYLVANIA

Anderson-Metcalf & Company, Inc.

BOSTON, MA.

SCALE IN MILES



MAP BASED ON U.S.G.S. 7.5 MINUTE QUADRANGLE
SHEET FRANKLIN, N.J. 1954. REVISED 1971.

JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

Determine Time of Concentration

method #1 Texas Highway methodOverland Flow

Reach length = 1000 ft

$$\text{slope} = \frac{1310 - 1250}{1000} = 0.06 = 6.0\%$$

From Table "Woodlands"

ave. Velocity = 2.0 fps

$$1000 \div 2.0 \text{ fps} = 500 \text{ sec} = 8.3 \text{ min} = .14 \text{ hr}$$

Channel Flow

no channel

method #2 Soil & water conservation

$$L = 0.6 T_c$$

$$L = \frac{f^{0.8} (4.1)^{1.67}}{9000 y^{0.5}}$$

$$S = \frac{1000}{4.1} - 10$$

Take $C_1 = 70$ for woods

$$S = \frac{1000}{70} - 10 = 4.3$$

$$L = 1000 + 0 = 1000 \text{ ft.}$$

$$y = \frac{1310 - 1250}{1000} = 0.06 = 6.0\%$$

$$L = \frac{(1000)^{0.8} (4.3 + 1)^{1.67}}{9000 (6)^{0.5}} = .18 \text{ hours}$$

$$T_c = \frac{.18}{.6} = 0.30 \text{ hours}$$

JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALEMethod #3 SCS TR #55Overland

length = 1,000 ft

head = 60 ft

slope = 0.06 = 6.0%

from Figure 3-1 page 3-2

 $V = .60 \text{ fps}$

$$T_c = \frac{L}{V} = \frac{1,000}{0.6} = 1,667 \text{ sec} = 27.8 \text{ min} = .46 \text{ hr}$$

Method #4 Kirby methodOverland flow

$$T_c = 0.83 \left(\frac{Nl}{\sqrt{s}} \right)^{0.467}$$

 $N = 0.6$ $s = 0.06$ $l = 1,000$

$$T_c = 0.83 \left(\frac{(0.6)(1000)}{\sqrt{0.06}} \right)^{0.467} = 31.75 \text{ min} = .53 \text{ hrs}$$

average T_c from 4 methods

$$\frac{.14 \text{ hr} + .39 \text{ hr} + .46 \text{ hr} + .53 \text{ hr}}{4} = .36 \text{ hrs}$$

$$\text{Lag} = T_L = 0.6 \times .36 = .22 \text{ hrs}$$

JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29
1/4 IN. SCALEStage Versus Discharge

Hydraulic profile on page 4. Numbers in circles (①, ②, etc.) refer to section numbers from page 4.

Spillway - 3-12" pipes, inverts at 1250.0.

$$Q = C A \sqrt{2g} \sqrt{H}$$

$$C = 0.61$$

$$A = 3 \left(\frac{\pi}{4} \right) = 2.36 \text{ ft}^2$$

$$\sqrt{H} = \sqrt{E - 1250.5}$$

$$Q = 0.61(2.36) \sqrt{64.4} (E - 1250.5)^{1/2} = 11.55 (E - 1250.5)^{1/2}$$

Top of dam (sections 2, 3, 4, 5, & 6)

Discharge will be calculated at 1238.0, 1250.0, 1251.1, 1251.2, 1251.4, 1251.6, 1251.8, 1252.0, 1252.5, 1253.0. $C = 2.7$ for dam crest, $Z = Z_H:1V$

Z Description

45.5 Section ② is a 100-ft. sloping weir, avg. ht. 1252.4, ends at 1251.3 & 1251.7


500 Section ③ is a 100-foot sloping weir, avg. ht. 1251.2, ends at 1251.1 & 1251.3

166.7 Section ④ is a 100-foot sloping weir, avg. ht. 1251.4, ends at 1251.1 & 1251.7

250 Section ⑤ is a 100-foot sloping weir, avg. ht. 1251.9, ends at 1251.7 and 1252.1

62.5 Section ⑥ is a 100-foot sloping weir, avg. ht. 1252.9, ends at 1252.1 and 1253.7

For a partially submerged sloping weir:




$$Q = C L_{\text{submerged}} H_{\text{ave}}^{3/2}$$


$$L_{\text{submerged}} = 2(E - E_{\text{low}})$$

$$H_{\text{ave}} = \frac{0.1(E - E_{\text{low}})}{0.5(E - E_{\text{low}})} = 0.5(E - E_{\text{low}})$$

$$\text{fully submerged sloping weir: } Q = C(z)(E - E_{\text{low}})^2 (0.5(E - E_{\text{low}}))^{3/2}$$



$$Q = C L H_{\text{ave}}^{3/2} = C L (E - E_{\text{avg}})^{3/2}$$



ANDERSON-NICHOLS

VERNON	BOSTON	CONCORD
Rock Island Lake Hydraulic Profile		
DATE 6/30/81	SCALE: 1"=100' 1"=100'	JOB NO. P. 406/14
SHEET NO. P. 406/14		

⊗ 1-24" pipe, d/s
invert at 12366.


JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALEfor $E = 1238.0, 1250.0, 1251.1$: $Q = 0.0$ for $E = 1251.2$: $Q = 2.7 (500) (E - 1251.1)^{(3)} (0.5(E - 1251.1))^{3/2}$ $+ 2.7 (166.7) (E - 1251.1)^{(4)} (0.5(E - 1251.1))^{3/2}$ for $E = 1251.4, 1251.6$: $Q = 2.7 (45.5) (E - 1251.3)^{(2)} (0.5(E - 1251.3))^{3/2}$ $+ 2.7 (100) (E - 1251.2)^{(3)} + 2.7 (166.7) (E - 1251.1)^{(4)} (0.5(E - 1251.1))^{3/2}$ for $E = 1251.8, 1252.0$: $Q = 2.7 (45.5) (E - 1251.3)^{(2)} (0.5(E - 1251.3))^{3/2} + 2.7 (100) (E - 1251.2)^{(3)}$ $+ 2.7 (100) (E - 1251.4)^{(4)} + 2.7 (250) (E - 1251.7)^{(6)} (0.5(E - 1251.7))^{3/2}$ for $E = 1252.5, 1253.0$: $Q = 2.7 (45.5) (E - 1251.3)^{(2)} (0.5(E - 1251.3))^{3/2} + 2.7 (100) (E - 1251.2)^{(3)}$ $+ 2.7 (100) (E - 1251.4)^{(4)} + 2.7 (100) (E - 1251.9)^{(6)} + 2.7 (62.5) (E - 1252.1)^{(6)} (0.5(E - 1252.1))^{3/2}$ Side Slopes (sections ① and ⑦)for 1238.0 - 1253.0 : $Q = 0$

JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

Elevation (Ft. above NGVD)	Description	Q spillway (CFS)	Q top of dam (CFS)	Q side slopes (CFS)	Q Total (CFS)
1238.0	approx. pond lwft.	0	0	0	0
1240.0		0	0	0	0
1250.0	spillway crest	0	0	0	0
1251.1	top of Dam	8.9	0	0	8.9
1251.2		9.7	2	0	11.7
1251.4		11	32	0	43
1251.6		12	98	0	110
1251.8		13	202	0	215
1252.0		14	348	0	362
1252.5		16	912	0	928
1253.0		18	1,716	0	1,734



JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALEStage Versus Storage


Surface Area at normal pool (1250.0) = 10 acres

Surface Area at elevation 1260 = 15.8 acres

Assume a linear increase in surface area with elevation. Assume

storage = 0.0 at 1238.0, 50 ac-ft. at 1250 (average depth = 5 feet).


Elevation (ft. above NGVD)	Surface Area (Acres)	Avg. S. A. (Acres)	Incremental Storage (Ac-Ft)	Cumulative Storage (Ac-Ft)
1238.0	-	-	-	0
1250.0	10	10.00	11.0	50
1251.1	10.06	10.09	1.0	61
1251.2	10.12	10.175	2.0	62
1251.4	10.23	10.29	2.1	64
1251.6	10.35	10.405	2.1	66.1
1251.8	10.46	10.52	2.1	68.2
1252.0	10.58	10.725	5.4	70.3
1252.5	10.87	10.985	5.5	75.7
1253.0	11.10			81.2



JOB NO.

SQUARES
1/4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40Overtopping Analysis

JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALEBreach Analysis

Assume breach width of 100'


Time to develop of 0.25 hour

Straight walls on breach

Bottom elevation of 1238' NGVD

The damage center is a pond about 500 feet downstream, with 3 houses around it, 2 about 5 feet above the pond and one about 15 feet up. The stream below Rock Island Dam actually routes around the pond to the north, beside the two lower houses.

The following cross section approximates the control at the dam:



$$Q = 3.0 (5) (H)^{3/2} + 2.7 (100) (H-1)^{3/2} + 2 (2.7) (10) (H-1) (0.5(H-1))^{3/2}$$

For storage, Assume 2 acre-ft at spillway crest, and large surface area $\rightarrow S = 2 + H(AcF_s/F_s)$. Assume constant surface area as pond rises (effect of pond storage on Q negligible anyway)

JOB NO.

QUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

	<u>H (ft above SL)</u>	<u>Q (CFS)</u>	<u>Storage (Ac-Ft)</u>
1			
2			
3			
4	0	0	2
5	1	15	3
6	2	332	4
7	3	950	5
8	4	1,821	6
9	5	2,939	7
10	6	4,306	8
11	7	5,930	9
12	8	7,815	10
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			

A HEC-1 shows that dam breach upon overtopping would have the following impact:

	<u>Flow</u>	<u>Stage</u>
Before failure	9 Cfs	0.6'
After failure	3,532 cfs	5.43'

This would cause about 0.4 feet of flooding at the two houses. Thus, the dam is considered to be significant hazard, since there is little threat of loss of life.

JOB NO.

SQUARES
4 IN. SCALE

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

Determination of "C" for
low level outlet

D = diameter = 8 inches

$n = 0.015$ for RCP (K+B 6-15)

A_p = area of pipe opening = 0.35

L_p = length of pipe = 60 feet

K_f = friction loss through pipe

$$K_f = \frac{5087n^2}{D^{4/3}} = \frac{5087(.015)^2}{(8)^{4/3}} = .072$$

K_L = entrance loss to pipe = 0.8 (K+B 6-18)

C_p = coefficient of discharge

$$C_p = A_p \sqrt{\frac{2g}{1 + K_L + K_f L_p}} = .35 \sqrt{\frac{64.4}{1 + .8 + (.051)(60)}} = 1.14$$

$$C = C_p / A_p / \sqrt{2g}$$

$$= 1.14 / .35 / \sqrt{64.4} = 0.40$$

JOB NO.

SQUARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
1/4 IN. SCALE

Drawdown by low level outlet

Assume: ① no significant inflow

② one 8" pipe

③ invert estimated at 1240.0 NGVD

④ $Q_p = C_p H^{\frac{1}{2}} = 1.14 H^{\frac{1}{2}}$ ⑤ $\text{Acre-ft/day} = 1.9835 \times Q_{\text{ave}}$ ⑥ $\text{Days} = \Delta \text{storage} / \text{Acre-ft/day}$

Elev (NGVD)	Storage (acre-ft)	ΔS	H (ft)	Q (cfs)	Ave Q (cfs)	Acre-ft day	Days
1250	60		9.7	3.6			
		10			3.4	6.7	1.5
1248	40		7.7	3.2			
		10			2.95	5.9	1.7
1246	30		5.7	2.7			
		10			2.45	4.9	2.0
1244	20		3.7	2.2			
		10			1.85	3.7	2.7
1242	10		1.7	1.5			
		10			.75	1.5	6.7
1240.3	0		0				

14.6 day

APPENDIX 4

HEC 1 OUTPUT

ROCK ISLAND LAKE

LINE	1D	1	2	3	4	5	6	7	8	9	10
1	RUCK ISLAND LAKE DAM	19	OVERSICP ANALYSIS	15	TOM CONUCH	ANCO					
2	NEW JACKLEY DAM TEST	019	SUSSEX COUNTY	15	SPARTA TOWNSHIP						
3	DETAILED RUN OF	NO. 1	FLOOD WITH	0.5	PMF FROM	24-HOUR	PHF				
4		5		300							
5	FLOW	0.5									
6											
7	AL DEVELOP	INFLOW	HYDROGRAPH	TO	ROCK ISLAND LAKE	DAM					
8	INFLOW FROM	SCS UNIT	GRAPH COMPUTATIONS								
9	0.07	0.27		1	NO	113	123	132			
10	22.2										
11	0.22										
12											
13	A2 ROUTE	INFLOW	HYDROGRAPH	THROUGH	ROCK ISLAND LAKE						
14	STOR	50.0									
15	0.0	125.0		62	1251.4	66.1	68.2	70.3	75.7	81.2	
16	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
17	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
18	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
19	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
20	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
21	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
22	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
23	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
24	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
25	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
26	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
27	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
28	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
29	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
30	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
31	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
32	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
33	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
34	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1251.6	1252.3	1252.5	1253.4	
35	123.0	125.0	1251.4	1251.2	1251.6	1251.6	1				

 * FLOOD HYDROGRAPH PACKAGE (HEC-1) *
 * FEBRUARY 1981 *
 *
 * RUN DATE 07/02/81 TIME 16.38.33 *

 * U.S. ARMY CORPS OF ENGINEERS *
 * THE HYDROLOGIC ENGINEERING CENTER *
 * 609 SECOND STREET *
 * DAVIS, CALIFORNIA 95616 *
 * (916) 440-3285 OR (FIS) 448-3285 *

ROCK ISLAND LAKE DAM OVERTOPPING ANALYSIS TOM GOOCH ANCO
 NEW JERSEY CIVIL NO. 819 - SUSSEX COUNTY - SPARTA TOWNSHIP
 DETAILED RUN OF TEST FLOOD WITH 0.5 PMF FROM 24-HOUR PMF

5 10 OUTPUT CONTROL VARIABLES PRINT CONTROL
 IPRI 1 PLOT CONTROL
 IPLOI 0 HYDROGRAPH PLOT SCALE
 QSCAL 0 YLS PRINT DIAGNOSTIC MESSAGES

17 HYDROGRAPH TIME DATA 5 MINUTES IN COMPUTATION INTERVAL
 IDATE 1 0000 STARTING DATE
 ITIME 0 0000 STARTING TIME
 IDO 300 NUMBER OF HYDROGRAPH ORDINATES
 NDATE 2 0055 ENDING DATE
 NDTIME 0 0055 ENDING TIME

COMPUTATION INTERVAL 0.08 HOURS
 TOTAL TIME BASE 24.92 HOURS

ENGLISH UNITS
 ORIGIN, AREA, DEPTH, ELEVATION, ELEVATION
 LENGTH, ELEVATION
 SURFACE VOLUME
 SURFACE AREA
 TEMPERATURE
 SQUARE MILES
 FEET
 FEET PER SECOND
 FEET
 FEET
 DEGREES FAHRENHEIT

JP MULTI-PLAN OPTION 1 NUMBER OF PLANS
 JN MULTI-PLAN OPTION 1
 PLOT OF RUNOFF
 0.50

7 KK DEVELOP INFLOW HYDROGRAPH TO ROCK ISLAND LAKE DAM

 * A1 *

INFLOW FROM SCS UNIT GRAPH COMPUTATIONS

9 BA SUBBASIN CHARACTERISTICS
 TAFLA 0.09 SUBBASIN AREA

10 BF BASE FLOW CHARACTERISTICS
 STFC 0.27 INITIAL FLOW
 GFCSC 0.27 BEGIN BASE FLOW RECESSON
 FTRR 1.00000 RECESSON CONSTANT

PRECIPITATION DATA

11 PM - PROBABLE MAXIMUM STORM
 PMS 22.20
 TRSDC 0.80
 TRSDA 0.09
 TRSD 0.09
 SCS 0.09
 INDEX PRECIPITATION
 TRANSPORTATION COEFFICIENT
 TRANSPORTATION AREA
 USE SCS DISTRIBUTION

PERCENT OF INDEX PRECIPITATION OCCURRING IN GIVEN TIME
 6-HR 123.0
 12-HR 113.0
 24-HR 132.0
 46-HR 0.0
 72-HR 0.0
 96-HR 0.0

12 LU UNIFORM LOSS RATE 1.00
 STRL 0.10
 CNSTL 0.0
 RTIMP 0.0
 INITIAL LOSS RATE
 UNIFORM IMPERVIOUS AREA

13 UD SCS DIMENSIONLESS UNITGRAPH
 LAG 0.22

UNIT HYDROGRAPH
 15 END-OF-PERIOD ORDINATES
 33. 54. 0.

35. 120. 166. 146. 20. 12. 7.

HYDROGRAPH AT STATION A1

DA	MON	HRMN	GPD	KATH	LOSS	EXCESS	COMP	Q	DA	MON	HRMN	ORD	RAIN	LOSS	EXCESS	COMP	Q
00																	

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

.....

[illegible]

0210	63	0.	138	6.	1	1740	13	62.	1	2235	288	3.
0220	64	0.	139	6.	1	1750	14	62.	1	0000	289	2.
0230	65	0.	140	6.	1	1755	15	61.	1	0005	290	1.
0240	66	0.	141	6.	1	1800	16	61.	1	0010	291	1.
0250	67	0.	142	6.	1	1805	17	58.	1	0015	292	1.
0300	68	0.	143	6.	1	1810	18	58.	1	0020	293	1.
0310	69	0.	144	6.	1	1815	19	54.	1	0025	294	0.
0320	70	0.	145	6.	1	1820	20	54.	1	0030	295	0.
0330	71	0.	146	8.	1	1825	21	53.	1	0035	296	0.
0340	72	0.	147	17.	1	1830	22	53.	1	0040	297	0.
0350	73	0.	148	29.	1	1835	23	51.	1	0045	298	0.
0400	74	0.	149	39.	1	1840	24	4.	1	0050	299	0.
0410	75	0.	150	46.	1	1840	25	4.	1	0055	300	0.

PEAK FLOW (CFS) 369.
 TIME (HR) 15.75
 MAXIMUM AVERAGE FLOW 24-HR 24.92-HR
 6-HR 9.24 72-HR 24
 (INCHES) 9.435 10.438
 (AC-FT) 46. 50.
 CUMULATIVE AREA = 0.09 SQ MI

ROUTE INFLOW HYDROGRAPH THROUGH ROCK ISLAND LAKE

HYDROGRAPH ROUTING DATA

14 KK	15 RS	16 SV	17 SE	18 SQ	19 SE	20 SS	21 ST
STORAGE	STORAGE	STORAGE	ELEVATION	DISCHARGE	ELEVATION	SPILLWAY	TOP OF DAM
0.0	0.0	0.0	1238.00	0.	1238.00	1250.00	1251.10
50.00	50.00	50.00	1251.10	0.	1251.00	3.00	500.00
WORKING R AND D COEFFICIENT	NUMBER OF SURREACHES	TYPE OF INITIAL CONDITION	TYPE OF INITIAL CONDITION	TYPE OF INITIAL CONDITION	TYPE OF INITIAL CONDITION	TYPE OF INITIAL CONDITION	TYPE OF INITIAL CONDITION
0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
61.0	61.0	61.0	62.0	62.0	62.0	62.0	62.0
64.0	64.0	64.0	64.0	64.0	64.0	64.0	64.0
66.1	66.1	66.1	66.1	66.1	66.1	66.1	66.1
70.3	70.3	70.3	70.3	70.3	70.3	70.3	70.3
75.7	75.7	75.7	75.7	75.7	75.7	75.7	75.7
81.2	81.2	81.2	81.2	81.2	81.2	81.2	81.2
1252.00	1252.00	1252.00	1252.00	1252.00	1252.00	1252.00	1252.00
1252.50	1252.50	1252.50	1252.50	1252.50	1252.50	1252.50	1252.50
1253.00	1253.00	1253.00	1253.00	1253.00	1253.00	1253.00	1253.00
928.	928.	928.	928.	928.	928.	928.	928.
1734.	1734.	1734.	1734.	1734.	1734.	1734.	1734.
1252.00	1252.00	1252.00	1252.00	1252.00	1252.00	1252.00	1252.00
1252.50	1252.50	1252.50	1252.50	1252.50	1252.50	1252.50	1252.50
1253.00	1253.00	1253.00	1253.00	1253.00	1253.00	1253.00	1253.00

SPILLWAY CREST ELEVATION
 SPILLWAY WIDTH
 WEIR COEFFICIENT
 EXPONENT OF HEAD
 ELEVATION AT TOP OF DAM
 DAM WIDTH
 WEIR COEFFICIENT
 EXPONENT OF HEAD

STORAGE	0.0	50.00	61.00	62.00	65.00	66.10	68.20	70.30	75.70	81.20
OUTFLOW	0.0	0.0	8.90	11.70	43.00	110.00	215.00	362.00	928.00	1734.00

HYDROGRAPH AT STATION
PLAN 1, RATID = 0.50 A2

[illegible]

PEAK FLOW AND STAGE (END-OF-PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND, AREA IN SQUARE MILES
 TIME TO PEAK IN HOURS

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO	1
HYDROGRAPH AT	A1	0.09	1	369	0.50
				15.75	
ROUTED TO	A2	0.09	1	288	
				15.92	
			** PEAK STAGES IN FEET **		
			1	1251.90	
				15.92	

SUMMARY OF DAM OVERTOPPING/BREACH ANALYSIS FOR STATION A2

PLAN 1

RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1250.00 50. 0.	SPILLWAY CREST 1250.00 50. 0.	TOP OF DAM 1251.61 9.	DURATION OVER TOP HOURS	MAXIMUM OUTFLOW CFS	MAXIMUM STORAGE AC-FT	MAXIMUM DEPTH OVER DAM	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.50	1251.90					6.75	280.	69.	0.80	15.92	0.0

*** NORMAL END OF JOB ***

PEAK FLOW AND STAGE (END-OF-PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CFS IN CLUTIC FEET PER SECOND, AREA IN SQUARE MILES
 TIME TO PEAK IN HOURS

OPERATION	STATION	AREA	PLAN	TIME	RATIOS APPLIED TO FLOWS			
					RATIO 1 0.10	RATIO 2 0.25	RATIO 3 0.50	RATIO 4 1.00
HYDROGRAPH AT	A1	0.09	1	FLH	74	184	369	738
				TIME	15.75	15.75	15.75	15.75
PCLTEC TO	A2	0.09	1	FLH	6	68	268	640
				TIME	18.25	16.17	15.92	15.83
** PEAK STAGES IN FEET					1251.90	1251.90	1252.25	1252.25
1					1251.90	1251.90	1252.25	1252.25
TIME					16.25	16.17	15.92	15.83



PLAN 1

SUMMARY OF DAM OVERTOPPING/BREACH ANALYSIS FOR STATION A2

	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1250.00	SPIGWAY CREST 1250.00	TOP OF DAM 1251.10					
RATIO OF PHF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH DOWN DAM	MAXIMUM STORAGE AC-FY	MAXIMUM OUTFLOW CFS	CREATION OVER HOURS	TIME OF MAX FLOWS	TIME OF FAILURE		
0.10	1250.79	0.00	58.	0.	0.0	18.25	0.0		
0.20	1251.48	0.00	69.	0.	0.0	16.17	0.0		
1.00	1252.25	1.15	73.	640.	8.75	15.63	0.0		

*** NORMAL END OF JOB ***

10.....1.....2.....3.....4.....5.....6.....7.....8.....9.....10

ROCK ISLAND LAKE DAM BREACH ANALYSIS TOM GOOCH ANCO
 NEW JERSEY DAM NO. 819 - SUSSEX COUNTY - SPARTA TOWNSHIP
 1 0 100

AL INFLOW HYDROGRAPH FOR ROCK ISLAND LAKE

ROUTE, INFLOW HYDROGRAPH THROUGH ROCK ISLAND LAKE

FLON	8.8	6.2	6.4	6.6	6.8	7.0	7.2
0	125.0	125.1	125.2	125.3	125.4	125.5	125.6
1	125.0	125.1	125.2	125.3	125.4	125.5	125.6
2	125.0	125.1	125.2	125.3	125.4	125.5	125.6
3	125.0	125.1	125.2	125.3	125.4	125.5	125.6
4	125.0	125.1	125.2	125.3	125.4	125.5	125.6
5	125.0	125.1	125.2	125.3	125.4	125.5	125.6
6	125.0	125.1	125.2	125.3	125.4	125.5	125.6
7	125.0	125.1	125.2	125.3	125.4	125.5	125.6
8	125.0	125.1	125.2	125.3	125.4	125.5	125.6
9	125.0	125.1	125.2	125.3	125.4	125.5	125.6

ROUTE, OUTFLOW TO DAMAGE-CENTER

FLIGHT	8.8	5.0	6.0	7.0	8.0	9.0	10.0
1	3.0	4.0	5.0	6.0	7.0	8.0	9.0
2	1.0	2.0	3.0	4.0	5.0	6.0	7.0
3	0.0	1.0	2.0	3.0	4.0	5.0	6.0
4	0.0	1.0	2.0	3.0	4.0	5.0	6.0
5	0.0	1.0	2.0	3.0	4.0	5.0	6.0
6	0.0	1.0	2.0	3.0	4.0	5.0	6.0
7	0.0	1.0	2.0	3.0	4.0	5.0	6.0
8	0.0	1.0	2.0	3.0	4.0	5.0	6.0
9	0.0	1.0	2.0	3.0	4.0	5.0	6.0
10	0.0	1.0	2.0	3.0	4.0	5.0	6.0

 * U.S. ARMY CORPS OF ENGINEERS *
 * THE HYDROLOGIC ENGINEERING CENTER *
 * 609 SECOND STREET *
 * DAVIS, CALIFORNIA 95616 *
 * (916) 440-3285 DR (FIS) 44R-3285 *

 * FLOOD HYDROGRAPH PACKAGE (HLC-1) *
 * FEBRUARY 1981 *
 *
 * RUN DATE 07/07/81 TIME 17.06.58 *

ROCK ISLAND LAKE DAM BREACH ANALYSIS TOM GOOCH ANCO
 NEW JERSEY DAM NO. 219 - SUSSEX COUNTY - SPARTA TOWNSHIP

4 IO OUTPUT CONTROL VARIABLES PRINT CONTROL
 IPLOT 1 PLOT CONTROL
 QSCAL 0 HYDROGRAPH PLOT SCALE
 QMSG YES PRINT DIAGNOSTIC MESSAGES

17 --- HYDROGRAPH TIME DATA 1 MINUTES IN COMPUTATION INTERVAL
 IN IN 1 STARTING DATE
 IOATE 1 STARTING TIME
 ITIME 1 0000 NUMBER OF HYDROGRAPH ORDINATES
 NO 100
 NDATE 1 0139 ENDING DATE
 NDTIME 0139 ENDING TIME

COMPUTATION INTERVAL 0.02 HOURS
 TOTAL TIME BASE 1.65 HOURS

ENGLISH UNITS AREA SQUARE MILES
 PRECIPITATION DEPTH INCHES
 LENGTH, ELEVATION FEET
 FLOW, VOLUME CUBIC FEET PER SECOND
 STORAGE AREA ACRES
 SURFACE AREA ACRES
 TEMPERATURE DEGREES FAHRENHEIT

5 PK 3 A1 6 INFLOW HYDROGRAPH FOR ROCK ISLAND LAKE

0 BA SUBBASIN PUNOFF DATA
 SUBBASIN CHARACTERISTICS SUBBASIN AREA
 AREA 0.0

HYDROGRAPH AT STATION A1

LA MCN	HRMN	ORD	FLOW	DA MCN	HRMN	ORD	FLOW	DA MCN	HRMN	ORD	FLOW	DA MCN	HRMN	ORD	FLOW
0000	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0001	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0002	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0003	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0004	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0005	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0006	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0007	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0008	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0009	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0010	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0011	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0012	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0013	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0014	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0015	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0016	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0017	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0018	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0019	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0020	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0021	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0022	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0023	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
0024	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5

EAK FLOW (CFS) 50.0
 TIME (HR) 0.07
 (INCHES) 0.000
 (AC-FT) 0.000
 MAXIMUM AVERAGE FLOW 75.49
 6-HR 24-HR 1.65-HR
 4.9 8.9 0.000
 0.000 0.000 0.000
 CUMULATIVE AREA = 0.0 SQ MI

7 KK ROUTE INFLOW HYDROGRAPH THROUGH ROCK ISLAND LAKE

8 KD OUTPUT CONTROL VARIABLES
 PRINT CONTROL
 PLOT CONTROL
 HYDROGRAPH PLOT SCALE

9 RS STORAGE ROUTING
 STPS
 ITYP
 RSVIC

LA MCN	HRMN	ORD	FLOW	DA MCN	HRMN	ORD	FLOW	DA MCN	HRMN	ORD	FLOW	DA MCN	HRMN	ORD	FLOW
10 SV	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
11 SE	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
12 SO	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5
13 SE	1	2	3	4	5	6	7	8	9	0	1	2	3	4	5

14 SS SPILLWAY 1250.00 SPILLWAY CREST ELEVATION
 SPILLWAY WIDTH 3.00
 SPILLWAY COEFFICIENT 1.50
 EXPONENT OF HEAD

15 ST TOP OF DAM 1251.10 ELEVATION AT TOP OF DAM
 DAM WIDTH 500.00
 DAM COEFFICIENT 0.0
 EXPONENT OF HEAD 1.50

16 SB BREACH DATA 1238.00 ELEVATION AT BOTTOM OF BREACH
 BREACH WIDTH 100.00
 BREACH COEFFICIENT 0.0
 EXPONENT OF HEAD 0.25
 TIME FOR BREACH TO DEVELOP 1251.10
 N.S. ELEVATION TO TRIGGER FAILURE
 FAIL

STORAGE 0.0 50.00 61.00 81.90 11.70 43.00 110.00 215.00 362.00 928.00 1734.00


OUTFLOW 0.0 0.0 0.0 8.90 11.70 43.00 110.00 215.00 362.00 928.00 1734.00


EGIN DAP FAILURE AT 0.10 HOURS

HYDROGRAPH AT STATION A2

PCN	HRMN	ORD	OUTFLOW	STORAGE	DA MON	HRMN	ORD	OUTFLOW	STORAGE	STAGE	DA MON	HRMN	ORD	OUTFLOW	STORAGE	STAGE
0000	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0001	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0002	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0003	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0004	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0005	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0006	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0007	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0008	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0009	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0010	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0011	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0012	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0013	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0014	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0015	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0016	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0017	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0018	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0019	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0020	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0021	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0022	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0023	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0024	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0025	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0026	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0027	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0028	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0029	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0030	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0031	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0032	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0033	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0034	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0035	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0036	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0037	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0038	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0039	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0040	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0041	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0042	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0043	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0044	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0045	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0046	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0047	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0048	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0049	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0050	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0051	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0052	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0053	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0054	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0055	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0056	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0057	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0058	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0059	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0060	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0061	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0062	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0063	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0064	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0065	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0066	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0067	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0068	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0069	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0070	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0071	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0072	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0073	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0074	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0075	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0076	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0077	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0078	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0079	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0080	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0081	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0082	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0083	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0084	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0085	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0086	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0087	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0088	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0089	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0090	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0091	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0092	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0093	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0094	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0095	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0096	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0097	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0098	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0099	1	2														

STATION A2





*** ** ** ** **

* A3 *

ROUTE OUTFLOW TO DAMAGE CENTER

18 KD OUTPUT CONTROL VARIABLES
PRINT CONTROL
1. PRINT CONTROL
2. PLOT CONTROL
0. HYDROGRAPH PLOT SCALE

HYDROGRAPH ROUTING DATA

19 RS STORAGE ROUTING
1. NUMBER OF SUBREACHES
2. TYPE OF INITIAL CONDITION
8.80 INITIAL CONDITION
0.0 WORKING R AND D COEFFICIENT

	2.0	3.0	4.0	5.0	6.0	7.0	8.0	9.0	10.0
20 SV STORAGE	0.0	1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00
21 SE ELEVATION	0.0	15.	332.	950.	1821.	2939.	4306.	5930.	7815.
22 SO DISCHARGE	0.0	1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00
23 SE ELEVATION									

STORAGE 2.00 3.00 4.00 5.00 6.00 7.00 8.00 9.00 10.00
OUTFLOW 0.0 15.00 332.00 950.00 1821.00 2939.00 4306.00 5930.00 7815.00

** WARNING ** MODELED PULS ROUTING WILL BE NUMERICALLY UNSTABLE FOR OUTFLOWS BETWEEN 4306. TO 7815.

PEAK FLOW (CFS) 3532.	TIME (HR) 0.33	(CFS) (INCHES) (AC-FT)	6-HR 482. 0.000 66.	24-HR 482. 0.000 66.	MAXIMUM AVERAGE FLOW 72-HR 482. 0.000 66.
AK STORAGE (AC-FT) 7.	TIME (HR) 0.33	6-HR 4.	24-HR 4.	MAXIMUM AVERAGE STORAGE 72-HR 4.	1.65-HR 4.
PEAK STAGE (FEET) 5.43	TIME (HR) 0.33	6-HR 1.76	24-HR 1.76	MAXIMUM AVERAGE STAGE 72-HR 1.76	1.65-HR 1.76

CUMULATIVE AREA = 0.0 50 MI

RUNOFF SUMMARY
FLOW IN CUBIC FEET PER SECOND
TIME IN HOURS, AREA IN SQUARE MILES

OPERATION	STATION	PEAK FLOW	TIME OF PEAK	AVERAGE FLOW 6-HOUR	AVERAGE FLOW 24-HOUR	PERIOD 72-HOUR	BASIN AREA	MAXIMUM STAGE	TIME OF MAX STAGE
HYDROGRAPH AT	A1	50.	0.07	49.	49.	49.	0.0		
ROUTED TO	A2	3537.	0.32	486.	486.	486.	0.0	1251.11	0.12
ROUTED TO	A3	3532.	0.33	482.	482.	482.	0.0	5.43	0.33

SUMMARY OF DAM OVERTOPPING/BREACH ANALYSIS FOR STATION A2

PLAN 1									
RATIO OF PHF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVERTOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	TOP OF DAM	
								INITIAL VALUE	SPILLWAY CREST
1.00	1251.11	0.01	61.	3537.	0.06	0.32	0.10	1251.09 1251.61 9.	1250.00 1251.10 14013.

* NORMAL END OF JOB ***

APPENDIX 5

REFERENCES

ROCK ISLAND LAKE

APPENDIX 5
REFERENCES

ROCK ISLAND LAKE DAM

Buddington and Baker, The Geology of Franklin and part of Hamburg Quadrangles, New Jersey, 1961.

Chow, Ven Te, Open Channel Hydraulics, McGraw Hill Book Company, New York, 1959.

King, H.W. and E.F. Brater, Handbook of Hydraulics, McGraw Hill Book Company, New York, Fifth Edition 1963.

Salisbury, Kummel, Peet and Whitson, Glacial Drift Map of New Jersey, 1902.

Schway, G.O., R.K. Frevert, T.W. Edmister, and K.K. Barnes, Soil and Water Conservation Engineering, The Ferguson Foundation Agricultural Engineering Series, John Wiley and Sons, Inc., New York, 1966, 683 pp.

U.S. Army Corps of Engineers, Hydrologic Engineering Center, Flood Hydrograph Package (HEC-1) Users Manual Preliminary, Davis, California, March 1981.

U.S. Department of Agriculture, Soil Conservation Service, Urban Hydrology for Small Watersheds, Technical Release No. 55, Washington, 1975.

U.S. Department of Commerce, Weather Bureau, "Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1000 Square Miles and Durations of 6, 12, 24, and 48 Hours", Hydrometeorological Report No. 33, Washington.

United States Department of Interior, Bureau of Reclamation, Design of Small Dams, U.S. Government Printing Office, Washington, 1977, 816 pp.

U.S. Department of Interior, Geological Survey, 7.5-Minute Series (topographic) maps, scale 1:24000, Contour Interval 20 feet: Franklin, New Jersey, (1954), Photorevised 1971.

Viessman, Warren, Jr., J.W. Knapp, G.L. Lewis, T.E. Harbaugh, Introduction to Hydrology, Harper and Row, Publishers, New York, Second Edition 1977, 704 pp.

DATE
FILMED
- 8